Road Name	Fire Number	Direction from #	Description	QTY of patches	Cost
Crestwood Dr.	110000	A 4 11			
	N3006	At #	Middle of Road broken area	4	\$600
	N3006	At #	Concrete edge hole	3	\$450
	N3048	Across from #	De-Lam hole	1	\$150
Otter Dr.					
	N2809	Toward Lake	Recently filled hole 1, Broken dip 5	6	\$900
	N2812	At #	Small holes in edge of old repair	3	\$450
	N2875	At #	2 by #, 1 across	3	\$450
	N2887	Toward Culvert	2 on De-lamination, 2 on cullvert dip	4	\$600
	N2929	Either side of drive	Edge breaking up 8 to South, 2 to North	10	\$1,500
	N2973	Across fron #	Edge breaking up	4	\$600
	N3023	At #	Several holes / broken spots	3	\$450
	N3040	At #	Various holes / broken	9	\$1,350
Pine Ridge Ln.					
	On Otter Seam	Road transition	Mastic coming out, hole starting	2	\$300
	East Landing	In landing	80' starting at concrete and 1 on seam	17	\$2,550
Vestgate Acres Rd.	01	0	Destruction of OF com-	_	A.=-
	Shamrock Corner	On corner	Broken dipped SE corner	3	\$450 \$750
	E1894	At end of driveway By Mailbox	Broken area on odge	5	\$750 \$450
	E1891 E1960	Out from driveway	Broken area on edge Broken area in middle of road	3 5	\$450 \$750
	E1980	Driveway and to West	Holes and broken	11	\$1.650
	E1981	East of Driveway	Holes and broken in middle	2	\$300
	E2035	Across and to West	Edge broken to middle	8	\$1,200
	E2051	Across and to East	Broken and holes 75' strip	15	\$2,250
	E2059	At # and strip to East	One at #, 45' strip to East	11	\$1,650
Erickson Rd.					
	E1751	West	Culvert dip, flush to surrounding road	5	\$750
River Wood Dr.					
	Intersection	East of River Rd.	Culvert heaved. Add to smooth	6	\$900
	E1518	By Mailbox	Middle of road broken	6	\$900
	E1564	At driveway	Road broken up, big section	11	\$1,650
	E1644	To East	Culvert heaved X2, 6 each to smooth	12	1,800
Covered Bridge Rd.	110000				0450
	N3368	Across from #	One hole by mailbox	1	\$150
	N3395	At #	Several small holes in middle	3	\$450
Larson Rd.	N3345	At #	One small hole in middle	1	\$150
	E1219	In front of driveway	De-lam hoe	4	\$600
	Brainerd Corner	SW edge	Hole on corner	2	\$300
	Q intersection	Seam with driveway	Water hold hole	3	\$450
	E2388	At # and to East	1 hole at #, and 5 at De-lam to East	6	\$900
laase Rd.					
IUUJE INU.	E1198	West	Rough patch in middle	4	\$600
	E1768	East in Woods section	Several dips and small holes	6	\$900
	E1652	At #	couple of holes	2	\$300
	E1402	East of #	Dip / hole	1	\$150
River Rd.			•		
	N3931	To North	1 at Power box, 3 across culvert dip	4	\$600
Dakland Rd.					
	N4440	South of #	Middle of road small holes	2	\$300
Julie Ln.				_	
	E2317	By Mailbox	Several holes in middle	3	\$450
	E2341	At #	Hole in middle Previously filled	2	\$300
			Totals		
				216 patches	\$32,400
		repairs each			